
VAN'S AIRCRAFT, INC.



This service letter details inspection of RV-12 aft fuselage bulkheads for minor cracking. Only RV-12 Emp/Cone Kits shipped prior to December 4, 2008 are affected by this Service Letter.

<u>Step 1</u>: Inspect the circled regions for cracks in the 3/16 in. interior flanges of the parts depicted in Figure 1. Also inspect the left-handed parts; F-1208-L, F-1209-L, F-1210A-L (not shown).




FIGURE 1: INSPECTION AREA

(ALSO APPLIES TO F-1208-L, F-1209-L, F-1210A-L)

If cracks are found that do not extend into the radius of the flange they should be removed using the following method.

<u>Step 2</u>: Notch the flange just enough to remove the crack. This may be accomplished using a round file or a notching tool if available. See Figure 2.




FIGURE 2: CRACK REMOVAL

PAGE 1 of 2 | RV-12 | DATE: 12/8/08


VAN'S AIRCRAFT, INC.

A part with a crack that extends into the radius of the flange should be repaired using the following method.

Step 3: Remove the crack as described in Step 2.

Fabricate a patch from the full size template shown in Figure 3.

Increase part width to 1-1/2 in. if crack is adjacent to stiffening bead.



FULL SIZE TEMPLATE (FLAT PATTERN)






FIGURE 3: FABRICATE PATCH

 $\underline{\text{Step 4}}$: Center the patch over the notch. Space the flange of the patch so that it is close to but not contacting the part flange. Match-Drill the patch to the web of the part using the patch as a guide. Remove the patch and deburr the web of the part. Cleco the patch in place.




FIGURE 4: INSTALL PATCH




FIGURE 5: COMPLETED REPAIR

PAGE 2 of 2 RV-12 DATE: 12/8/08