

TOTAL PERFORMANCE VAN'S AIRCRAFT

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

NOTIFICATION 14-09-25

Date Released: Sept 25, 2014
Date Effective: Sept 25, 2014
Subject: Optional vernier throttle upgrade
Affected Models: RV-12
Required Action: Remove and replace non-vernier throttle cable assembly with vernier throttle cable assembly.
Time of Compliance: Optional installation
Supercedes Notice: NA

Labor Required / SLSA Warranty Allowance: NA

Level of Certification: ELSA - Owner, LSR-I , A&P
SLSA - A&P with RFSC iRMT 912 Service Specialty or
LSR-M with RFSC iRMT 912 Service Specialty

Synopsis:

Removes the previous friction lock version of the throttle cable and adds a throttle cable with vernier.

Method of Compliance:

NOTE: KAI Section 50 references the installation of both the CT DUAL THROTTLE-12 and CT DUAL THROTTLE-12V.

Step 1: Remove the CT DUAL THROTTLE-12 per KAI Section 50.

Step 2: Install the CT DUAL THROTTLE-12V per KAI Section 50.

Step 3: Perform the Carburetor Synchronization procedure per the RV-12 Maintenance Manual, Chapter 12.

Step 4: Perform the Verify Function of Throttle Return Springs Procedure per the RV-12 Maintenance Manual, Chapter 12.

Step 5: Make a logbook entry indicating compliance with Notification 14-09-25.

Step 6: Place a copy of this notification in the back of the maintenance manual for your aircraft. Note the addition of this notification to the bottom of the Maintenance Manual table of contents.

Part Numbers:

CT DUAL THROTTLE-12V

TOTAL PERFORMANCE
VAN'S AIRCRAFT

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm