

# VAN'S AIRCRAFT, INC.

14401 NE Keil Road, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • [www.vansaircraft.com](http://www.vansaircraft.com) • [info@vansaircraft.com](mailto:info@vansaircraft.com)

---

Service Letter: May 18, 2006

Subject: C-1014 door handle spur gear

Affected Models: RV-10 only

A number of C-1014 door handle spur gears were shipped in RV-10 Finish Kits without the roll-pin hole drilled in them (see diagram and Drawing 45-13 of your plans).



Please inspect your C-1014 spur gears to assure they have been drilled to accept the MS16562-42 roll-pin. If you find that the gears you received are **not** drilled, please return them to Van's Aircraft for replacement.

If you have questions regarding this letter, please contact Van's Technical Support at: 503 678-6545 or....[support@vansaircraft.com](mailto:support@vansaircraft.com)

We apologize for any inconvenience this has caused.