

14401 Keil Road NE, Aurora, Oregon, USA 97002
PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com
Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

NOTIFICATION 14-07-03

Date Released: July 3, 2014

Date Effective: July 3, 2014

Subject: FAA Special Airworthiness Information Bulletin (SAIB) HQ-14-16 regarding MS 21042

all-metal lock nuts.

Affected Models: All Van's Aircraft RV Models

Required Action: Inspect installed hardware. Replace defective hardware.

Time of Compliance: At or before the next annual condition inspection

Supersedes Notice: None

Labor Required / SLSA Warranty Allowance: N/A

Level of Certification: N/A

Synopsis: This notification is intended to make owners and operators of all Van's Aircraft RV models aware of FAA Special Airworthiness Information Bulletin (SAIB) HQ-14-16 regarding MS 21042 all metal lock nuts.

Method of Compliance: Van's Aircraft recommends that owners and/or operators of all RV models comply with the applicable recommendations in SAIB HQ-14-16.

Link to SAIB HQ-14-16:

http://www.rotor.com/rotornews/April14/HQ-14-16.pdf