

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • <u>www.vansaircraft.com</u> • <u>info@vansaircraft.com</u> Service Letters and Bulletins: <u>www.vansaircraft.com/public/service.htm</u>

NOTIFICATION 15-09-21

Date Released: Sept 21, 2015

Date Effective: Sept 21, 2015

Subject: SkyView Autopilot/Knob Modules

Affected Models: RV-12

Required Action: Install Modules for enhanced AP/EFIS operation

Time of Compliance: N/A

Supercedes Notice: N/A

Labor Required / SLSA Warranty Allowance: 4.0 Hours / None

Level of Certification: Owner: LSA Repairman Inspection

SLSA: LSA Repairman Maintenance, A&P

Synopsis:

This notification allows the installation Dynon AP & Knob modules.

Method of Compliance:

Step 1: Buy the RV-12 SV AP-KNOB KIT and install the modules in accordance with KAI Section 58

Step 2: Update aircraft Weight and Balance data in accordance with KAI Section 58.

Step 3: Make a logbook entry indicating compliance with Notification 15-09-21.

Step 8: Place a copy of this notification in the back of the maintenance manual for your aircraft.

Note the addition of this notification to the bottom of the Maintenance Manual table of contents.

PART NUMBER

Qty	Item	
1.000	AV SV-AP/KNOB PANEL	
1.000	WH-00105	HARNESS
1.000	F-00073	TEMPLATE
8.000	MS21071L06	632 NUT PLATE
0.005	AN426AD3-4	RIVETS (LB)
1.000	ES HST-3/16X1'	HEAT SHRINK TUBE