

November 16, 2007

MASTER SWITCH SNAFU

Our supplier of ES 2GK54-73 Master Switches sent us a batch of different switches that will not work as we intended. We received these switches October 2, 2007 and started shipping them shortly thereafter. If you received a switch between October 2 and November 25, 2007, check to be sure you have the correct switch.

The incorrect switch has small copper jumper straps in a “X” pattern on the back. In the correct switch there are no jumper wires. If jumper straps are found, cut them away. The switch will then operate as intended.

