



VAN'S AIRCRAFT
TOTAL PERFORMANCE

14401 Keil Road NE, Aurora, Oregon, USA 97002
PHONE 503-678-6545 • FAX 503-678-6560
www.vansaircraft.com • info@vansaircraft.com

REASON FOR REVISION

Product Description: RV-12 Pilot's Operating Handbook (POH)

Documentation change for RV-12 original/legacy model: Additional steps added to various RV-12 emergency procedures to correspond with latest RV-12iS procedures.

List of Changes

RV-12 POH Rev 15, Front Cover:

Change: "Rev 15" was "Rev 14" and "03/28/19" was "12/12/18"

RV-12 POH Rev 15, Pages i-iv:

Change: "Rev 15" was "Rev 14" and "03/28/19" was "12/12/18"

RV-12 POH Rev 15, Page iii, Revision Summary table:

Cover Page ii, iii, iv: Change: Rev "15" was "14" and "03/28/19" was "12/12/18"

In Section 3: Change: Rev "8" was "7" and "03/28/19" was "12/12/18"

Front Cover: Change: Rev "15" was "14" and "03/28/19" was "12/12/18"

Rear Cover: Change: Rev "15" was "14" and "03/28/19" was "12/12/18"

RV-12 POH Rev 15, Section 3 REV 8

Page 3-3:

Added: "Fuel Pump" Fuse – PULL – REMOVE

Page 3-4:

Added: 30A "Gen Main Bus" Fuse – PULL – REMOVE

Added: "Fuel Pump" Fuse – PULL – REMOVE

Page 3-7:

Change: Contents completely replaced with RV-12iS POH (R3) sub-section: 12iS "ENGINE FAILURE ON TAKE-OFF"

Page 3-12:

Added: "Fuel Pump" Fuse – PULL – REMOVE

Added: 30A "Gen Main Bus" Fuse – PULL – REMOVE

Page 3-13:

Added: "Fuel Pump" Fuse – PULL – REMOVE

Added: Master Switch – OFF

Added: 30A "Gen Main Bus" Fuse – PULL – REMOVE

RV-12 POH Rev 15, Rear Cover:

Change: "Rev 15" was "Rev 14" and "03/28/19" was "12/12/18"