



VAN'S AIRCRAFT
TOTAL PERFORMANCE

14401 Keil Road NE, Aurora, Oregon, USA 97002
PHONE 503-678-6545 • FAX 503-678-6560
www.vansaircraft.com • info@vansaircraft.com

RV-10 Change: 10CX 02-20-18-1 (RV-10 Wheel Pant Standoff)

REASON FOR REVISION / NEW PRODUCT NAME AND DESCRIPTION:

The previous wheel pant standoff tended to fail over time. A new one-piece standoff is stronger, lower weight and has fewer parts to install (one part replaces 6 parts).

REVISION DESCRIPTION / NEW DOCUMENTATION:

KAI Page 46-01 REV 1: Shows the correct depiction of the new standoff U-01004.

KAI Page 46-05 REV 2: In Figure 1 shows the correct depiction of the new standoff U-01004.

In Step 2 and Step 4 "U-1004A" should be "U-01004"

Delete Step 3.

Delete Figure 2.

Renumber the steps on the page.

KAI Page 48-04 REV 1: In Figure 1 shows the correct depiction of the new standoff U-01004.

KAI Page 48-05 REV 1: In Figure 1 and Figure 3 shows the correct depiction of the new standoff U-01004.

KAI Page 48-06 REV 1: In Figure 1 shows the correct depiction of the new standoff U-01004.

In Step 1 "U-1004B" should be "U-01004".

KAI Page 48-07 REV 2: In Figure 1 shows the correct depiction of the new standoff U-01004.