

VAN'S AIRCRAFT

TOTAL PERFORMANCE

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

NOTIFICATION 18-10-18

Date Released: October 18, 2018

Date Effective: October 18, 2018

Subject: Skyview Dual Display Installation

Affected Models: RV-12iS

Affected Serial Numbers: SLSA: SN 12075 and later
ELSA: All fuselage kits shipped after August, 2017

Required Action: Optional Installation

Time of Compliance: Optional Installation

Supersedes Notice: N/A

Labor Required / SLSA Warranty Allowance: 3.0 Hours / N/A

Level of Certification: Owner: LSA Repairman Inspection
SLSA: LSA Repairman Maintenance, A&P

Synopsis:

This notification allows the installation of a second co-pilot EFIS screen.

Materials Required:

The following materials are required to complete the steps necessary to achieve compliance with this Notification:

- a. Purchase from Van's Aircraft. Part no. RV-12 AV-SVT-HDX DUAL-IS

Method of Compliance:

Step 1: Complete Section 43BiS/U

Step 2: Make a logbook entry indicating compliance with N 18-10-18.

Step 3: Place a copy of this notification in the back of the maintenance manual for your aircraft. Note the addition of this notification to the bottom of the Maintenance Manual table of contents.