

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • <u>www.vansaircraft.com</u> • <u>info@vansaircraft.com</u>
Service Letters and Bulletins: <u>www.vansaircraft.com/public/service.htm</u>

NOTIFICATION 18-10-19

Date Released: October 19, 2018

Date Effective: October 19, 2018

Subject: Garmin Dual Display Installation

Affected Models: RV-12iS

Affected Serial Numbers: SLSA: SN 12075 and later

ELSA: All fuselage kits shipped after August, 2017

Required Action: Optional Installation

Time of Compliance: Optional Installation

Supersedes Notice: N/A

Labor Required / SLSA Warranty Allowance: 3.0 Hours / N/A

Level of Certification: Owner: LSA Repairman Inspection

SLSA: LSA Repairman Maintenance, A&P

Synopsis:

This notification allows the installation of a second co-pilot EFIS screen.

Materials Required:

The following materials are required to complete the steps necessary to achieve compliance with this Notification:

a. Purchase from Van's Aircraft, Part no. RV-12 AV-G3XT DUAL-IS

Method of Compliance:

Step 1: Complete Section 43CiS

Step 2: Make a logbook entry indicating compliance with N 18-10-19.

<u>Step 3:</u> Place a copy of this notification in the back of the maintenance manual for your aircraft. Note the addition of this notification to the bottom of the Maintenance Manual table of contents.