

14401 Keil Road NE, Aurora, Oregon, USA 97002 PHONE 503-678-6545 • FAX 503-678-6560 www.vansaircraft.com • info@vansaircraft.com

SERVICE LETTER 19-10-30

Date Released:	October 30, 2019
Date Released.	

Date Effective: October 30, 2019

Subject: Optional RV-12iS Throttle Grip

Affected Models: RV-12iS

Affected Serial Numbers: All RV-12iS model aircraft

Required Action: Optional

Time of Compliance: Optional

Supersedes Notice: N/A

Labor Required / SLSA Warranty Allowance: N/A

Level of Certification: Owner, LSA Repairman Maintenance, A&P (not applicable to E-LSA)

Synopsis:

An optional alternate throttle grip is available to install on all RV-12iS aircraft.

Materials Required:

The following materials are required to complete the steps necessary to achieve compliance with this Notification.

a. Purchase from Van's Aircraft: Qty. 1 KIT 12iS THROTTLE GRIP



Method of Compliance:

Step 1: Remove the two CT-01205 T-Handles. Refer to KAI 49iS-08 or 49U-08.




FIGURE 1: REMOVE THE CT-01205

Step 2: Install the F-12140-L and F-12140-R using the hardware shown below.




FIGURE 2: INSTALL THE F-12140-L AND -R

<u>Step 3:</u> Make a logbook entry indicating compliance with SL 19-10-30 per the requirements of the controlling authority.

Place a copy of this notification in the back of the maintenance manual for your aircraft. Note the addition of this notification to the bottom of the Maintenance Manual table of contents.