



## SERVICE LETTER 19-12-31

**Date Released:** February 3<sup>rd</sup>, 2020

**Date Effective:** January 3<sup>rd</sup>, 2020

**Subject:** Optional Three Blade Sensenich Propeller

**Affected Models:** All RV-12, RV-12iS

**Affected Serial Numbers:** All

**Required Action:** None

**Time of Compliance:** None / Optional

**Supersedes Notice:** None

**Labor Required / SLSA Warranty Allowance:** Not Applicable

**Level of Certification:** ELSA: Aircraft Owner  
SLSA: LSA Repairman Maintenance or A&P

**Synopsis:** This service letter provides instructions for installation of a Sensenich Three Blade Composite Propeller.

**Materials Required:** The following materials are required to complete the steps necessary to achieve compliance with this Service Letter, SL 19-12-31.

a. Purchase from Van's Aircraft: Part no. 12 PROP KIT – 3 BLADE SENS

**Method of Compliance:**

Step 1: Part PROP 2A0R5R70EN-V and its associated parts and hardware must be replaced with PROP 3Y0R5 C70MY and its associated parts and hardware provided. Refer to KAI: RV-12, Section 47 or RV-12iS, Section 47iS and RV-12iS, Section 47AiS/U.

Step 2: Make a logbook entry indicating compliance with SL 19-12-31 per the requirements of the controlling authority. Record should include part numbers and serial numbers IN/OUT. Change to weight and balance is negligible.

Place a copy of this notification in the back of the maintenance manual for your aircraft. Note the addition of this notification to the bottom of the Maintenance Manual table of contents.