



## SERVICE BULLETIN SB-00045

**Date Released:** August 30, 2021

**Date Effective:** August 30, 2021

**Subject:** RV-12iS Lock Washer on Generator Wiring Clamp

**Affected Models:** All RV-12iS aircraft using a Rotax 912iS engine  
See Rotax SB-915 i-009iS/SB-912 i-012iS for the list of affected engine serial numbers

**Required Action:** Mandatory completion of Rotax SB-912 i-012iS

**Time of Compliance:** Refer to Rotax document SB-915 i-009iS/SB-912 i-012iS

**Labor Required / SLSA Warranty Allowance:** Refer to Rotax document

**Level of Certification:** Refer to Rotax document SB-915 i-009iS/SB-912 i-012iS

### Synopsis:

Van's Aircraft is issuing this Service Bulletin to ensure all RV-12iS owners are aware of and comply with Rotax SB-915 i-009iS/SB-912 i-012iS.

### Materials Required:

Refer to the following Rotax documents, which are available to download from the Rotax web site.

- [SB-915 i-009iS 912 i-012iS Inspection and or installation of lock washer A6](#)
- [SB-915 i-009 912 i-012 Inspection and or installation of lock washer A6](#)

### Method of Compliance:

Step 1: Complete Rotax SB-915 i-009iS/SB-912 i-012iS, which refers to specific steps included in SB-915 i-009/SB-912 i-012.

Step 2: Make a logbook entry indicating compliance with service document per the requirements of the controlling authority/agency.

Place a copy of this notification in the back of the maintenance manual for your aircraft. Add the name and date of the service information to the Addendum Documents List at the front of the Maintenance Manual.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and immediately notify Van's Aircraft, Inc. via email at [registrations@vansaircraft.com](mailto:registrations@vansaircraft.com).

Information regarding establishing/transferring aircraft ownership, registration and licensing is available at: <https://www.vansaircraft.com/qr/transfer-of-ownership/>