



SERVICE BULLETIN 00056

Date Released: May 19, 2022

Date Effective: May 19, 2022

Subject: Notification of Rotax SB-912i-013/SB-912i-013iS:
Replacement of Electrical Fuel Pump(s) for ROTAX
Aircraft Engines

Affected Models: RV-12iS using a Rotax 912iS Sport Engine

See Rotax SB-912i-013/SB-912i-013iS for the list of
affected fuel pump serial numbers

Required Action: Mandatory completion of Rotax SB-912i-013/SB-912i-
013iS

Time of Compliance: See Rotax SB-912i-013/SB-912i-013iS

Supersedes Notice: N/A

Labor Required / SLSA Warranty Allowance: See Rotax SB-912i-013/SB-912i-013iS

Level of Certification: See Rotax SB-912i-013/SB-912i-013iS

Synopsis:

Van's Aircraft is issuing this Service Bulletin to ensure all RV-12iS owners are aware of and comply with Rotax SB-912i-013/SB-912i-013iS.

Materials Required:

Refer to Rotax SB-912i-013/SB-912i-013iS

Method of Compliance:

Step 1: Complete Rotax SB-912i-013/SB-912i-013iS. In addition, reference Van's Aircraft RV-12iS KAI Section 27iS and RV-12iS Maintenance Manual Chapter 13, as required.

Step 2: Make a logbook entry indicating compliance with SB-00056 per the requirements of the controlling authority/agency. Indicate in the logbook entry note the serial numbers of the new pumps and the replaced pumps.

Place a copy of this notification in the back of the maintenance manual for your aircraft. Add the name and date of the service information to the Addendum Documents List at the front of the Maintenance Manual.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and immediately notify Van's Aircraft, Inc. via email at registrations@vansaircraft.com.

Information regarding establishing/transferring aircraft ownership, registration and licensing is available at: <https://www.vansaircraft.com/qr/transfer-of-ownership/>