



SERVICE BULLETIN 00073

Date Released:	February 3, 2023
Date Effective:	February 3, 2023
Subject:	Notification of Garmin Service Bulletin for G3X Touch Displays
Affected Models:	RV-12 and RV-12iS equipped with Garmin G3X Touch systems running G3X software versions 9.10 and previous
Required Action:	Mandatory completion of Garmin's Service Bulletin NO.: 22112 Rev A
Time of Compliance:	Refer to Garmin's Service Bulletin NO.: 22112 Rev B
Supersedes Notice:	N/A
Labor Required / SLSA Warranty Allowance:	Refer to Garmin's Service Bulletin NO.: 22112 Rev B
Level of Certification:	Refer to Garmin's Service Bulletin NO.: 22112 Rev B

Synopsis:

Van's Aircraft is issuing this Service Bulletin to ensure all RV-12iS and RV-12 owners are aware of and comply with Garmin's Service Bulletin NO.: 22112 Rev B

Materials Required:

Refer to Garmin's Service Bulletin NO.: 22112 Rev B, which is available from Garmin.

Method of Compliance:

Step 1: Complete Garmin's Service Bulletin NO.: 22112 Rev B

Step 2: Make a logbook entry indicating compliance with service document per the requirements of the controlling authority/agency.

Place a copy of this notification in the back of the maintenance manual for your aircraft. Add the name and date of the service information to the Addendum Documents List at the front of the Maintenance Manual.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and immediately notify Van's Aircraft, Inc. via email at registrations@vansaircraft.com.

Information regarding establishing/transferring aircraft ownership, registration and licensing is available at: <https://www.vansaircraft.com/qr/transfer-of-ownership/>