



SERVICE BULLETIN 00090

Date Released: November 6th, 2023
Date Effective: November 6th, 2023
Subject: Dynon SV-AP-PANEL Runaway Trim
Affected Models: All
Required Action: See Dynon Service Bulletin 104808-000
Time of Compliance: See Dynon Service Bulletin 104808-000
Supersedes Notice: None

Labor Required / SLSA Warranty Allowance: Not Applicable

Level of Certification: SLSA: LSA Repairman Maintenance or A&P
ELSA: Owner (certification not required)
Check the rules of the local controlling authority/agency and the operating limitations for your aircraft.

Synopsis:

Failures of the SV-AP-PANEL has resulted in non-functional trim or movements of the trim system that are not commanded.

Materials Required:

See Dynon Service Bulletin 104808-000

Method of Compliance:

Step 1: See Dynon Service Bulletin 104808-000

Step 2: Make a logbook entry indicating compliance with service document per the requirements of the controlling authority/agency.

Place a copy of this notification in the back of the maintenance manual for your aircraft. Add the name and date of the service information to the Addendum Documents List at the front of the Maintenance Manual.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and immediately notify Van's Aircraft, Inc. via email at registrations@vansaircraft.com.

Information regarding establishing/transferring aircraft ownership, registration and licensing is available at: <https://www.vansaircraft.com/qr/transfer-of-ownership/>