

On November 17, Van's performed structural tests on a horizontal stabilizer built with the mismanufactured RV-7/7A HS-710 angle recently described in a website service notice. This stabilizer proved satisfactory in all tests. Our findings indicate that the use of the mismanufactured part does not affect the function or safety of the horizontal stabilizer. BUILD ON!