

14401 Keil Road NE, Aurora, Oregon, USA 97002 PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

NOTIFICATION 16-07-28

Date Released: March 16, 2017

Date Effective: July 28, 2016

Subject: Dynon SkyView ADS-B In

Affected Models: RV-12

Required Action: Install SkyView ADS-B In

Time of Compliance: N/A

Supersedes Notice: N/A

Labor Required / SLSA Warranty Allowance: 7.0 Hours / None

Level of Certification: Owner: LSA Repairman Inspection

SLSA: LSA Repairman Maintenance, A&P

Synopsis:

This notification allows the installation of the Dynon SkyView ADS-B In solution.

Method of Compliance:

<u>Step 1:</u> Buy the RV-12 kit listed below and install in accordance with KAI Section 53. <u>Step 2:</u> Update your aircraft Weight and Balance data in accordance with KAI Section 53.

Step 3: Make a logbook entry indicating compliance with Notification 16-07-28.

<u>Step 4:</u> Place a copy of this notification in the back of the Maintenance Manual for your aircraft. Note the addition of this notification to the bottom of the Maintenance Manual table of contents.

PART NUMBER

Purchase from Van's Aircraft:

Qty Part Number Description

1 RV-12 ADS-B SKYVIEW KIT SKYVIEW ADSB-472 IN ONLY