

VAN'S AIRCRAFT

TOTAL PERFORMANCE

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

REVISION DESCRIPTION / NEW DOCUMENTATION:

Page 27iS-01 MEMO: Update depiction of F-12127D.

Page 27iS-03 REV 1: Remove AN911-2D; Add FLF-00021 and FLF-00022. Add Step 3.

Page 27iS-07 REV 1: Add to Step 1: "Final-Drill 5/16 in. [7.9 mm] the holes in three of the F-01276C-1."

Page 27iS-08 REV 1: Change length and geometry of F-12127D in Steps 1, 2, 3, and View A-A.

Length Is: 84 27/32 in., Was: 82 11/16 in.

Bends Are: 25°, 88.2°, 37.0°, 45.0°, 90.0°, Were: 25°, 86°, 97°.

Add to Step 5: "Ensure F-12127D has a minimum of ½ in. [12.7mm] clearance to the F-12108A while seated in the F-01276C-1."

Page 27iS-09 REV 1: Change F-12127D lengths and geometry of F-12127D in Figures 1, 2, and Iso View.

Page 27iS-10 MEMO: Update depiction of F-12127D.

Page 27iS-11 MEMO: Update depiction of F-12127D.

Page 27iS-12 MEMO: Update depiction of F-12127D.

Page 27iS-13 MEMO: Update depiction of F-12127D.