

# VAN'S AIRCRAFT, INC.

14401 N.E. KEIL RD. • AURORA, OREGON 97002 • (503) 678-6545

FAX (503) 678-6560



Attention RV-9A builders:

It has come to our attention that an error may have occurred in identifying and shipping the correct gear legs with some RV-9A Fuselage kits.

To verify that you have received the correct gear legs, simply measure the angle of the bend at the axle end of the leg. The correct legs should have a bend angle of 49.5 degrees. If the angle on your gear legs measures 43 degrees, you have received the incorrect gear legs and you should contact Van's for replacement.

**CAUTION:** Even the incorrect legs will slide into the gear leg socket and bolt up....this alone does not verify that you have the correct legs. The angle of the bend at the axle end must be measured to verify that the leg is correct.

If you find that you have received the incorrect legs, notify Van's for arrangements to replace the legs.

We apologize for any inconvenience this may cause.

Sincerely,

A handwritten signature in black ink, appearing to read "Scott Risan".

Scott Risan  
Technical Support  
Van's Aircraft, Inc.

