

VAN'S AIRCRAFT, INC.

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com
Service Letters and Bulletins: <http://www.vansaircraft.com/public/notices.htm>

SERVICE BULLETIN 12-1-30

Date Released: January 30, 2012
Date Effective: January 30, 2012
Subject: RV-12 Fuel Filler Placard
Affected Models: All RV-12 Document Kits shipped prior to January 26, 2012
Required Action: Install new PLA-00017 Placard below filler cap
Time of Compliance: At or before the next annual condition inspection

Synopsis:

To prevent operation with non-vented fuel cap. Install cautionary placard to inform pilot/operator of RV-12 aircraft that the fuel cap must be the modified vented T-406A.

Information advising this is also located in the POH and FTS. This placard further ensures that the personnel operating or servicing the aircraft will be informed of this information.

Method of Compliance:

Install the PLA-00017 (CAUTION! USE VENTED FUEL CAP!) placard below the fuel cap as shown in Figure 1, Section 51-06 rev 2.

REQUIRED PARTS: PLA-00017 BLACK or PLA-00017 WHITE (use color with most contrast to airplane paint)

Note:

Required placards have been mailed to RV-12 builder/owners who received their document kits prior to the above date. Placards will be included in document kits sent after the above date. Document kits are sent on request after all airframe kits have been purchased.