



VAN'S AIRCRAFT
TOTAL PERFORMANCE

14401 Keil Road NE, Aurora, Oregon, USA 97002
PHONE 503-678-6545 • FAX 503-678-6560
www.vansaircraft.com • info@vansaircraft.com

REASON FOR REVISION

Documentation required for the Rotax 912ULS and Rotax 912iS powered versions of the RV-12iS.

Product Description: RV-12iS Documentation Kit.

List of Changes

- **RV-12iS POH REV 3 Section 1.2:** Updated values to match the changes made to Table 5.7.1
- **RV-12iS POH REV 3 Section 3.7.6:** Editorial Changes
- **RV-12iS POH REV 3 Section 5.7.1:** The column for range was based on endurance. In the "912 iS Cruise Performance Notes" added the statement "... with recommended prop pitch."