



14401 Keil Road NE, Aurora, Oregon, USA 97002
PHONE 503-678-6545 • FAX 503-678-6560
www.vansaircraft.com • info@vansaircraft.com

REASON FOR REVISION:

A recent change to a fuel pressure sensors – removing specific sensor call outs from RV-14 KAI. Updated specified fuel pressure sensors for the RV-12 and RV-12iS.

REVISION DESCRIPTION / NEW DOCUMENTATION:

RV-12 KAI Page 45A-05 REV 3: Replaced sensor 101690-000 with ES 103755-000.

RV-12iS KAI Page 42MiS/U-24 REV 1: Replaced sensor ES 101692-000 with ES 103757-000.

RV-12iS KAI Page 42MiS/U-30 REV 1: Replaced sensor ES 101692-000 with ES 103757-000.

RV-14 KAI Page 43-03 REV 2: Removed callouts of specific sensor part numbers.

RV-14 KAI Page 43-04 REV 2: Removed callouts of specific sensor part numbers.

RV-14 KAI Page 43-05 REV 2: Removed callouts of specific sensor part numbers.

RV-14 KAI Page 48-07 REV 1: Removed callouts of specific sensor part numbers.

DOWNLOADS PAGE:

WH-00133 REV 6: (Replaces WH-00133 REV 5)

WH-00139 REV 5: (Replaces WH-00139 REV 4)

RELATED SERVICE INFORMATION DOCUMENTATION:

SB-00006 (published)