



VAN'S AIRCRAFT
TOTAL PERFORMANCE

14401 Keil Road NE, Aurora, Oregon, USA 97002
PHONE 503-678-6545 • FAX 503-678-6560
www.vansaircraft.com • info@vansaircraft.com

SERVICE LETTER 00018

Date Released: 10/06/20
Date Effective: 10/06/20
Subject: Addition of a knob to the Vent Door Subassembly
Affected Models: RV-12
Required Action: N/A
Time of Compliance: N/A
Supersedes Notice: N/A

Labor Required / SLSA Warranty Allowance: N/A

Level of Certification: SLSA: LSA Repairman Maintenance or A&P
ELSA: Owner (certification not required)
Check the rules of the local controlling authority/agency and the operating limitations for your aircraft.

Synopsis:

A hand knob is available for installation on the RV-12 Vent Door Subassemblies to aid in the actuation of the vent door. This letter documents the process of adding the knob in an existing, completed aircraft and ensures SLSA compliance for the addition.

Materials Required:

Purchase part no. BAG 3116

Method of Compliance:

Step 1: Download Section 23iS from the web and use instructions to install the knob.

Step 2: Make a logbook entry indicating compliance with service document per the requirements of the controlling authority/agency.

Place a copy of this notification in the back of the maintenance manual for your aircraft. Note the addition of this notification to the bottom of the Maintenance Manual table of contents.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and immediately notify Van's Aircraft, Inc. via email at registrations@vansaircraft.com.

Information regarding establishing/transferring aircraft ownership, registration and licensing is available at: <https://www.vansaircraft.com/qr/transfer-of-ownership/>