

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • <u>www.vansaircraft.com</u> • <u>info@vansaircraft.com</u> Service Letters and Bulletins: <u>www.vansaircraft.com/public/service.htm</u>

## **NOTIFICATION 17-09-12**

**Date Released:** October 20, 2017

**Date Effective:** October 20, 2017

**Subject:** Stabilator fiberglass tip installation

Affected Models: RV-12

Required Action: Optional Installation

Time of Compliance: Optional Installation

Supersedes Notice: N/A

Labor Required / SLSA Warranty Allowance: 4 Hours / N/A

Level of Certification: (Owner, LSA Repairman Inspection -not applicable to SLSA), LSA Repairman

Maintenance, A&P

Synopsis: This Notification allows the installation of fiberglass stabilator tips on the RV-12

## **Method of Compliance:**

Step 1: Purchase the 12 STABILATOR TIP FAIRING KIT.

Step 2: Complete installation in accordance with RV-12 Manual Section 12A.

Step 3: Make a logbook entry indicating compliance with Notification 17-09-12.

<u>Step 4:</u> Place a copy of this notification in the back of the maintenance manual for your aircraft. Note the addition of this notification to the bottom of the Maintenance Manual table of contents.

Part Number: 12 STABILATOR TIP FAIRING KIT