

VAN'S AIRCRAFT

TOTAL PERFORMANCE

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

REVISION DESCRIPTION / NEW DOCUMENTATION:

Page 27U-01 MEMO: Change ES-40105 Fuel Pump to ES-40135.

Page 27U-02 REV 2: Change ES-40105 Fuel Pump to ES-40135.

Page 27U-03 MEMO: Change ES-40105 Fuel Pump to ES-40135.

Page 27U-04 MEMO: Change ES-40105 Fuel Pump to ES-40135.

Page 27U-06 REV 1: Add to Step 1: "Final-Drill 5/16 in. [7.9 mm] the holes in three of the F-01276C-1."