

VAN'S AIRCRAFT

TOTAL PERFORMANCE

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

REVISION DESCRIPTION:

The following table describes the wire color changes:

WHT/ORN is now ORN

WHT/BLU is now BLU

WHT/GRN is now GRN

WHT (to extend the motor when connected to +V) is now GRY

WHT (to retract the motor when connected to +V) remains WHT

RV-10 & RV-14 Page OP 38-06 REV 2: In Step 10 "...swap...the two white wires..." should be "...swap the GRY and WHT wires..."

In Figure 1 change the wire colors to match the table listed above. GRY goes to Pin 4.

RV-14 Page 09-24 REV 1: In Step 10 "The two white wires may be inserted into either of the locations indicated." should be "The WHT and GRY wires may be inserted into either of the locations indicated."

In Figure 1 change the wire colors to match the table listed above. GRY goes to Pin 4.

WH-000125 (although this is a part it is also used as an instruction set):

WH-000125 RIGHT WING has moved to R2

WH-000125 TAILCONE LEFT has moved to R2