

VAN'S AIRCRAFT

TOTAL PERFORMANCE

14401 Keil Road NE, Aurora, Oregon, USA 97002

PHONE 503-678-6545 • FAX 503-678-6560 • www.vansaircraft.com • info@vansaircraft.com

Service Letters and Bulletins: www.vansaircraft.com/public/service.htm

NOTIFICATION 18-11-15

Date Released: November 15, 2018

Date Effective: November 15, 2018

Subject: SkyView Autopilot/Knob Modules

Affected Models: RV-12iS

Required Action: Install AP Servos and Modules for enhanced AP/EFIS operation

Time of Compliance: N/A

Supersedes Notice: N/A

Labor Required / SLISA Warranty Allowance: 2.1 Hours (Servos only) / NA
NOTE: For optional AV-SV-AP-PANEL and AV-SV-KNOB-PANEL installation include an additional 1.5 Hours.

Level of Certification: LSA Repairman Maintenance, A&P (not applicable to E-LSA)

Synopsis:

This notification allows the installation of the Skyview Autopilot Servo option and the AP/Knobs Panel option.

Method of Compliance:

Step 1: Download KAI RV-12iS Section 44AiS Manual and refer to same to purchase and install the appropriate components listed therein.

PART NUMBER

Purchase from Van's Aircraft:

<u>Qty</u>	<u>Part Number</u>	<u>Description</u>
1	RV-12 AP SERVO KIT-SV-IS	Autopilot Servo Kit
1	RV-12 SV AP-KNOB KIT-IS	Button/ Knob Module Kit
1	AV SV-AP/KNOB PANEL-IS	Button/ Knob