



SERVICE BULLETIN 00066

Date Released: October 21, 2022

Date Effective: October 21, 2022

Subject: Prohibited use of ethanol in Andair fuel pumps

Affected Models: All except RV-12 and RV-12iS

Required Action: Review Andair Service Alert - October 6, 2022

Time of Compliance: Before further flight

Supersedes Notice: N/A

Labor Required / SLSA Warranty Allowance: N/A

Level of Certification: N/A
Check the rules of the local controlling authority/agency and the operating limitations for your aircraft.

Synopsis:

Use of ethanol fuels with Andair fuel pumps may cause them to fail.

For a list of approved fuels and further information see Andair Service Alert – October 6, 2022, available from the Andair website.

Materials Required:

N/A

Method of Compliance:

Refer to Andair Service Alert – October 2022.

Place a copy of this notification in the back of the maintenance manual for your aircraft. Add the name and date of the service information to the Addendum Documents List at the front of the Maintenance Manual.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and immediately notify Van's Aircraft, Inc. via email at registrations@vansaircraft.com.

Information regarding establishing/transferring aircraft ownership, registration and licensing is available at: <https://www.vansaircraft.com/qr/transfer-of-ownership/>